




GB


UNITED KINGDOM

Diagram / Parts List

GA5100

Angle Grinder





GA5100 / Angle Grinder

Item	Sub	Parts No.	Parts Description	Qty	I/C	E/C No.	Close No.	Remark
001	D10	137018-9	Gear housing assembly	1				
			INC. 2-6					
002		417771-6	Pin cap	1				
003		233376-2	Compression spring 8	1				
004		213960-9	O-ring 5	1				
005		256546-6	Shoulder pin 4	1				
006		263002-9	Rubber pin 4	1				
007		266361-0	Binding head tapping screw 4X30	4				
008		252186-8	Hex. nut M6	1				
009		226861-2	Spiral bevel gear 10	1				
010		211092-6	Ball bearing 629DDW	1				
011		213445-5	O-ring 26	1				
012		317821-6	Gear housing cover	1				
013A		511B01-0	Armature assembly 115V	1				
013B		511B03-6	Armature assembly 220-240V	1				
	D10		INC. 14-20					
014		681636-0	Insulation washer	1				
015		253186-1	Flat washer 7	1				
016		210017-7	Ball bearing 607DDW	1				
017		422768-2	Labyrinth rubber ring 19	1				
018		267756-0	Wave washer 6	1				
019		688117-5	Magnet sleeve	1				
020		259039-2	Self lock 6	1				
021		266345-8	Binding head tapping screw 4X80	2				
022		457137-8	Baffle plate	1				
023A		621C81-5	Field	1			E1310	
023B		621C84-9	Field	1			E1310	
023-1A		621C86-5	Field	1	<	E1310		
023-1B		621C89-9	Field	1	<	E1310		
024		413R11-8	Motor housing	1				
025		413R14-2	Switch knob	1				
026		413R12-6	Switch lever	1				
027		233121-5	Compression spring 4	1				
028		8141P7-6	Name plate GA5100	1				
029		266007-8	Binding head tapping screw 3X10	2				
030A		194074-2	Carbon brush set CB-325	1				
030B		194074-2	Carbon brush set CB-325	1			E1310	
030-1B		194074-2	Carbon brush set CB-325	1	O	E1310		
031		644014-5	Brush holder	1				
032		644014-5	Brush holder	1				
033		8141P9-2	Serial No. label GA5100	1				
034		266007-8	Binding head tapping screw 3X10	2				
035		654544-8	Terminal block 1P	1			E1310	
036		654544-8	Terminal block 1P	1				
037		650046-2	Switch 1247.0304	1			E1462	
037-1		650046-2	Switch 1247.0304	1	O	E1462	E1310	
037-2		650086-0	Switch 1247.0305	1	<	E1310		
038A		620M11-3	Controller	1				
038B		620M12-1	Controller	1				
039		266385-6	Binding head tapping screw 4X14	1				
040		687682-1	Strain relief	1				
041		682566-8	Cord guard 10	1				
042A		665918-8	Power supply cord 1.0-2-2.5	1				
042B		692519-9	Power supply cord 1.0-2-2.5	1				
043		413R13-4	Rear cover	1				
044		266326-2	Binding head tapping screw 4X18	1				
045		210033-9	Ball bearing 696ZZ	1				
046		233950-6	Ring spring 11	1				
047		226862-0	Spiral bevel gear 37	1				
048		962151-6	Retaining ring (INT) R-32	1				
049		211129-9	Ball bearing 6201DDW	1				
050		267238-2	Flat washer 12	1				
051		213622-9	O-ring 45	1				
052		318331-6	Bearing box	1				
053		265099-4	Pan head screw M4X14	4				

A:GA5100(L)
B:GA5100(H)

Interchange
O : Yes
X : No
< : the new part can be substituted for the current.
> : the current part can be substituted for the new.
S : Interchangeable as a set.

GA5100 / Angle Grinder

[illegible]