


Позиция	Количество	Тип номер	Описание	PG
1	1	316097450	Gear housing compl.	27
2	1	316097590	Spindle stop compl.	13
3	4	141121640	Fill. head screw(DIN 7985)	11
4	4	141123940	Self-tap. fill. h. screw	11
5	1	316098810	Safety clutch w.pinion	31
6	1	341102460	Nut	13
7	1	316055080	Friction washer set compl.	23
8	2	141151120	Washer 10,2 X 14,8X 0,2	11
9	1	141152300	Washer 10,2 X 14,8X 0,1	12
10	1	141153920	Washer 10,2 X 14,8X 0,5	11
11	1	316054980	Bevel gear w.pinion	25
12	1	343450610	Flange	18
13	1	143195640	O-ring	11
14	1	339007800	Washer	11
15	1	341604420	Spindle M14	23
16	1	143192490	O-ring	12
17	2	339013140	Compensating Washer	11
18	1	342022040	Spring clip	11
19	1	316066040	Clamping lever compl.	22
20	1	341102660	Hex nut M7	11
21	1	143116020	Ball bearing, 8X 22X 7	14
22	1	141156650	Retaining ring	11
23	1	339007940	Washer	11
24	1	339153550	Baffle	11
25	1	310012730	Armature compl.,230V	33
26	1	343431690	Tacho disc	13
27	1	143115040	Ball bearing, 6x19x6	18
28	1	344114190	Rubber bushing	11
29	1	339151290	Baffle	11
30	1	314000540	Handle cpl.	22
31	1	311012880	Field w.coil,230V	29
32	1	315013930	Motor housing	20
33	1	338070350	Rating plate	13
34	1	316097610	Brush holder compl.	20
35	1	316097800	Carbon brush set	20
36	1	141116020	Self-tap fill h screw	12
37	1	343362490	Cable clip	12
38	1	343446470	Motor cap	16
39	2	141118730	Self-tap. fill. h. screw	11
40	1	343446380	Cable sleeve	11
41	1	344530000	Cable with plug	27

Позиция	Количество	Тип номер	Описание	PG
42	1	343446480	Switch rod	11
43	1	343437100	Switch slide	11
44	1	338122540	Metabo plate	11
45	1	343086580	Electronic unit,230V 50/60Hz	31
46	1	343410270	Switch 2-pole,X2	21
47	1	339204500	Wheel guard,D125	20
48	1	341031160	Clamping flange	22
49	1	316055350	Clamping nut compl.,M14	22
880	1	344130910	Grease 100G	24
885	1	344130560	Grease SF 011 50Gr 1,8oz	30
1001	1	338506460	diagram	



магазин
БАШ

МАЙСТОРА

ПРОФЕСИОНАЛНИ РЕШЕНИЯ