



Position	Amount	Type number	Description	PG
1	1	315015210	Motor housing	22
2	1	338136370	Type label	12
3	4	141113180	Self-tap. fill. h. screw	11
4	1	338129960	Indication label, CAS	12
5	4	141116020	Self-tap fill h screw	12
6	1	316040610	Spindle stop compl.	14
7	1	316097510	Gear housing compl.	25
8	1	141130100	Hexagonal nut	11
9	1	316071370	Bevel gear and pinion	20
10	1	143116020	Ball bearing, 8X 22X 7	14
11	1	315420080	Fixed bearing cover	11
12	2	141110460	Fillister head screw	11
13	1	339007940	Washer	11
14	1	330002260	Fan	12
15	1	343459730	Sealing washer	12
16	1	310013700	Armature compl.	31
17	1	316076750	Armature compl.,	36
18	1	311013780	Field coil compl.	32
19	1	339011530	Cloth Label	12
20	1	343087290	Micro switch	21
21	1	343090590	Electronic unit, 18V	47
22	2	342004180	Pressure spring	11
23	1	338080370	Rating plate 02374000 W18 L BL 9-125	12
24	3	141120070	Fill. head screw	11
25	1	343454590	Switch slide	19
26	1	343458570	Switch rod	12
27	1	342004000	Tension spring	11
28	1	314000540	Handle cpl.	22
29	1	316047590	Clamping lever compl.	23
30	1	339060160	Compensating Washer	12
31	1	141156520	Washer	11
32	1	344097550	O-ring 48 x 1	11
33	1	341605710	Spindle M14	17
34	1	339007790	Washer	11
35	1	143192540	O-ring	11
36	1	316071360	Flange compl.	26
37	1	339203490	Wheel guard, D 125	26
38	1	341031160	Clamping flange	22
39	1	341106900	Flange nut	20
40	1	344163920	Pin spanner	14
44	1	316066720	Latch compl.	14

Position	Amount	Type number	Description	PG
45	1	343447510	Locking slide	11
46	3	341213440	Shrink hose	11
95	1	343439680	Cover cap	11
880	1	344130910	Grease 100G	24
1001	1	338506800	Wiring diagram	



МАГАЗИН
БАШ МАЙСТОРА
ПРОФЕСИОНАЛНИ РЕШЕНИЯ